


## Replacement Parts Diagram

Model - HBH850-CE (Series A-H)

**PROPRIETARY RIGHTS NOTICE** This document and all information contained within it is the property of Hamilton Beach Brands, Inc. (HBB). It is confidential and proprietary and has been provided to you for a limited purpose. It must be returned or destroyed upon request. Disclosure, reproduction or use of this document and any information contained within it, in full or in part, for any purpose is forbidden without the prior written consent of HBB. No photographs may be taken of any article fabricated or assembled from this document without the prior written consent of HBB.



### For Quiet Shield Repair Kit

Thread Insert – 990099100


Thumb Screw - 990099000

|                                                                        |                       |           |                                   |         |              |           |      |   |
|------------------------------------------------------------------------|-----------------------|-----------|-----------------------------------|---------|--------------|-----------|------|---|
| <b>Hamilton Beach</b><br>4421 Waterfront Drive<br>Glen Allen, VA 23060 | Revision Description: |           | Changed Lower housing part number |         |              |           |      |   |
|                                                                        | Request Number:       | HQE-11746 | Revision Date:                    | 5/11/11 | Approved by: | HQE-11746 |      |   |
|                                                                        | Issue Code(s):        | SP, CS    | Page:                             | 1 of 2  | Document #:  | 510019600 | Rev: | U |


## Replacement Parts Diagram

Model - HBH850-CE (Series A-H)

**PROPRIETARY RIGHTS NOTICE** This document and all information contained within it is the property of Hamilton Beach Brands, Inc. (HBB). It is confidential and proprietary and has been provided to you for a limited purpose. It must be returned or destroyed upon request. Disclosure, reproduction or use of this document and any information contained within it, in full or in part, for any purpose is forbidden without the prior written consent of HBB. No photographs may be taken of any article fabricated or assembled from this document without the prior written consent of HBB.



RFI Board  
990078800




Post  
990078900



Cordset Socket Plug  
990114900



Brush Motor Kit  
990075300  
(Set is 2 pcs)



Jar Sensor  
990084400

|                                                                        |                       |           |                                   |         |              |           |      |   |
|------------------------------------------------------------------------|-----------------------|-----------|-----------------------------------|---------|--------------|-----------|------|---|
| <b>Hamilton Beach</b><br>4421 Waterfront Drive<br>Glen Allen, VA 23060 | Revision Description: |           | Changed Lower housing part number |         |              |           |      |   |
|                                                                        | Request Number:       | HQE-11746 | Revision Date:                    | 5/11/11 | Approved by: | HQE-11746 |      |   |
|                                                                        | Issue Code(s):        | SP, CS    | Page:                             | 2 of 2  | Document #:  | 510019600 | Rev: | U |